- 1. Give number of sheets needed.
- 2. Give gauge or thickness of metal.
- 3.Kind of metal.
- 4. Give size of perforation, shape, centers and arrangement of holes.
- 5.Size of sheet.
- 6. Submit sketch or print when possible.